



Service Info



Over-running alternator pulley 59804

Visual differences

Manufacturer: BMW

Models: 1* (E81/E82/E87/E88)
3* (E90/E91/E92/E93)

Engines: N43

Part no.: 59804



Figure 1: Previous design



Figure 2: New design

As part of our continuous efforts to improve our products, modifications have been made to the over-running alternator pulley with part number 59804.

This Service Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the transition period, we may have mixed stocks of both types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

info@ruville.de

www.ruville.com/en/

* Calls from within the UK 08457 001100

